

| Line | Oper | Description | Part Number | Qty | Extended Price \$ | Labor | Paint | |
|------------------|----------------------------------|-------------|--------------------------------------------------|----------------|-------------------|-------------|------------|--|
| 1 | # | Rpr | Pre-Repair diagnostic scan | | | 0.5 | | |
| 2 | # | Subl | Pre-Repair diagnostic scan | 1 | 50.00 X | | | |
| 3 | # | Subl | Post-Repair diagnostic scan | 1 | 70.00 X | | | |
| 4 | # | Rpr | Post-Repair diagnostic scan | | | 0.5 | | |
| 5 | FRONT BUMPER & GRILLE | | | | | | | |
| 6 | | O/H | front bumper | | | 3.2 | | |
| 7 | <> | Repl | Bumper cover | NZ6Z17757SAPTM | 1 | 746.87 | Incl. 2.4 | |
| 8 | | | Add for Clear Coat | | | | 1.0 | |
| 9 | | | Add for distance sens | | m | 0.3 | | |
| 10 | | Repl | LT Lower deflector | NZ6Z16B075A | 1 | 27.30 | Incl. | |
| 11 | | Repl | Lower cover w/o tow hook | NZ6Z17626AB | 1 | 418.43 | Incl. | |
| 12 | | Repl | LT Upper bracket | NZ6Z17C947B | 1 | 11.80 | Incl. | |
| 13 | | R&I | Grille assy | | | Incl. | | |
| 14 | FRONT LAMPS | | | | | | | |
| 15 | | Repl | LT Headlamp assy w/o accent lighting | NZ6Z13008C | 1 | 1,269.33 | 0.3 | |
| 16 | | | Aim headlamps | | | 0.5 | | |
| 17 | | Repl | LT Side marker lamp | NZ6Z13A565B | 1 | 58.08 | Incl. | |
| 18 | FENDER | | | | | | | |
| 19 | * | Rpr | LT Fender | | | 6.0 | 2.2 | |
| 20 | | | Overlap Major Non-Adj. Panel | | | | -0.2 | |
| 21 | | | Add for Clear Coat | | | | 0.4 | |
| 22 | * | Rpr | LT Apron/rail assy 2.0 liter w/o tow hooks (HSS) | | s | 4.0 | 0.5 | |
| 23 | | Repl | LT Fender liner | NZ6Z16103A | 1 | 92.50 | 0.5 | |
| 24 | | R&I | LT Nameplate "XL" | | | 0.3 | | |
| 25 | ELECTRICAL | | | | | | | |
| 26 | | Repl | Bracket | LX6Z12A659G | 1 | 67.33 | | |
| 27 | | Repl | Cover | LX6Z00810E | 1 | 39.67 | | |
| 28 | | Repl | ECM | M1PZ12A650EA | 1 | 986.67 m | 0.4 | |
| 29 | # | Repl | Flex Additive | | 1 | 6.00 T | | |
| 30 | # | Repl | Corrosion Protection | | 1 | 3.00 T | | |
| 31 | # | | Cover Car for Overspray | | 1 | 12.00 X | 0.3 | |
| 32 | # | Rpr | Disconnect Battery | | | | | |
| 33 | # | Rpr | Memory Function Reset | | | 0.5 | | |
| 34 | | | OTHER CHARGES | | | | | |
| 35 | # | | E.P.C. | 1 | 3.50 | | | |
| SUBTOTALS | | | | | 3,862.48 | 17.3 | 6.3 | |