

Safety Issue Type: Recalls

December 16 2021 NHTSA Campaign Number: 21V976000

Fuel Tank Damage/FMVSS 301

A damaged fuel tank may result in a fuel leak, increasing the risk of a fire.

NHTSA Campaign Number 21V976000

Manufacturer Ford Motor Company

Components FUEL SYSTEM, GASOLINE

Potential Number of Units Affected 5456

Summary

Ford Motor Company (Ford) is recalling certain 2022 Maverick vehicles. The fuel tank may have been damaged by drill holes during the installation of the spray-in bed-liner. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 301, "Fuel System Integrity."

Remedy

Dealers will inspect and replace the fuel tank as necessary, free of charge. Owner notification letters are expected to be mailed January 28, 2022. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 21C35.

Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Affected Products (1)

Vehicle

MAKE	MODEL	YEAR
FORD	MAVERICK	2022

Associated Documents (2)

Recall Acknowledgement

RCAK-21V976-7506.pdf 645.006KB

<https://static.nhtsa.gov/odi/rcl/2021/RCAK-21V976-7506.pdf>

Noncompliance Notice 573 Report

RCLRPT-21V976-9049.PDF 214.706KB

<https://static.nhtsa.gov/odi/rcl/2021/RCLRPT-21V976-9049.PDF>